NSSA®
NationalStormShelterAssociation

Certificate of Installation

Safe Room Produced by

Company Model # — SR01234

Company Model or Designation — NSSA Seal Number

Customer/Purchaser Information

Mr & Mrs Jack Weatherwise

Name

12322 Tornado Area

Street Address

Windy City — OK — 22331

City — State — Zip Code

Signature

Signed: Owner (optional)

GPS Coordinates: Insert Coordinates Here

Owner is advised to share with Fire Department and/or with Office of Emergency Management

EMBOSSED COMPANY SEAL

Compliance Statements

The producer of this Safe Room attests that the design, construction, and installation comply with the latest edition of **ICC-500 Standard**, **FEMA P-320** and **FEMA P-361** Guidelines.

Name of Third-Party Evaluator of design: Evaluator name/company

The Quality Assurance Plan with installation instructions and inspection schedule was shown on plans, or attached to them, and was followed. ☐ Yes ☐ No (check one)

IF NO: Installation instructions attached to this certificate were followed. ☐ Yes (check if applicable)

Safe Room Company — President /Owner — Date Signed

Signed: Producer or Representative — Title — Date

**Only required if NSSA Installer Member is used — Date Signed

Signed: Installer Member If Applicable — Date

Inspections

Required for all shelters with Type 4 Seal

May be required by Authority Having Jurisdiction or Grant Authority for Type 1 or Type 2 Seal

If applicable

Signed: Authority Having Jurisdiction or Grant Authority — Date

If applicable

Signed: Registered Design Professional — Registration No. — State(s)

PHOTO

Distribution of Certificate Copies

- Original to Owner
- Photocopies of Completed, Signed Certificate to:
  - NSSA Home Office
  - Authority Having Jurisdiction
  - Grant Authority if applicable

Location

GPS coordinates for this Safe Room are provided to NSSA to facilitate locating it for performance assessments should it be impacted by a severe wind storm. Information will be released by the NSSA only by permission of the owner or by court order. Location may be in public records for those safe rooms receiving grant funding.

Disclaimer

NSSA does not claim to have inspected, approved, or certified the quality of this safe room nor does NSSA warrant the performance of the shelter for general or any particular use.

© 2016