



Certificate of Installation

Safe Room Produced by

COMPANY MODEL #

03/01/2018

SR01234

Company Model or Designation

Date of Installation

NSSA Seal Number

Residential Installation *(check one)*

Community Installation — Occupancy: Up to 16 17-44 50-99 Over 100 - List Occupancy: _____

Customer/Purchaser Information

Mr. and Mrs Jack Weatherwise

Owner Name

12322 Tornado Area Way

Street Address

Windy City

Texas

23221

City

State

Zip Code

GPS Coordinates: **Insert Coordinates Here**

Owner is advised to share with Fire Department and/or with Office of Emergency Management

Compliance Statements

The producer of this Safe Room attests that the design, construction, and installation comply with the latest edition of **ICC/NSSA 500 Standard, FEMA P-320 and FEMA P-361** guidelines.

The Quality Assurance Plan with installation instructions and inspection schedule was shown on plans, or attached to them, and was followed. Yes No

IF NO: Installation instructions attached to this certificate were followed. Yes

Safe Room Company

President/Owner

Date signed

Signed: Producer or Representative

Title

Date

Only required if NSSA Installer Member is used

Date signed

Signed: Installer Member If Applicable

Date

Inspections (only if applicable)

Inspections performed and checklist completed by Producer Representative or Installer Member

— OR —

Authority Having Jurisdiction or Grant Authority performed inspection

Signed: Authority Having Jurisdiction or Grant Authority if inspected by one

Date

Distribution of Certificate Copies

- Original to Owner
- Photocopies of Completed, Signed Certificate to:
 - NSSA Home Office (P.O. Box 41166, Lubbock, TX 79409-1166)
 - Authority Having Jurisdiction
 - Grant Authority (if applicable)

Location

GPS coordinates for this Safe Room are provided to NSSA to facilitate locating it for performance assessments should it be impacted by a severe wind storm. Information will be released by the NSSA only by permission of the owner or by court order. Location may be in public records for those safe rooms receiving grant funding.

Disclaimer

NSSA does not claim to have inspected, approved, or certified the quality of this safe room nor does NSSA warrant the performance of the shelter for general or any particular use.